

Hello Idle Free Technician,

This month we would like to refresh your memory regarding NHTSA recalls 15E034 and 16E069. Recall 15E034 was initiated in 2015 and affects cracked frames and mounting hardware on the BA600 eAPU. Recall 16E069 was initiated in 2016 and affects our Reefer Link products sold with Anderson connectors. To date, many of these systems have not been remediated. If you run into one of these units, please ask the owner if you can make the repairs while the truck is in your shop.



Below is information to help you quickly identify affected units. For additional information, all documentation related to these recalls is posted in the dealer portal.

---

### NHTSA RECALL 15E034

Units with the following serial numbers have both defects A and B.

- 35Z12011401 to 35Z12090504
- 36Z12090701 to 36Z14050113

The serial number is located on the inside back wall of the APU (remove the cover) or on the outside of the unit, above the condenser fan.



Photographs of the defective parts are shown below as a reference.



Without Gusset (Defective)



With Gusset (Not Defective)

**DEFECT A**



**DEFECT B**

**Units with the following serial numbers have defect B only (as shown above)**

- 35Z12011401 to 35Z12090504
- 36Z12090701 to 36Z14050113
- 36X13111101 to 36X14050101
- 36X14050201 to 36X15042801

## NHTSA RECALL 15E034

Specifically, all Reefer Link kits with Anderson-Type Connectors are affected by this recall. If you see the following connector on any Idle Free Reeferlink systems. Please order the appropriate kit from Idle Free Systems and replace it.



As always, please direct your questions to our Technical Support team at (920) 206-9333 - ext 1.