

# Exhibit A1

---

Units with the following serial numbers have both defects A and B.

- 35Z12011401 to 35Z12090504
- 36Z12090701 to 36Z14050113

The serial number is located on the inside back wall of the APU (remove the cover) or on the outside of the unit, above the condenser fan.



Photographs of the defective parts are shown below as a reference.



Without Gusset (Defective)



With Gusset (Not Defective)

Defect A



Defect B

Additional Information:

- If you have not received your upgrade kits within 1 week of receiving this letter, please order through the dealer portal or contact Idle Free at [warranty@idlefreesystems.com](mailto:warranty@idlefreesystems.com) to order kit # 91705. The kits will include all required parts and installation instructions.
- Please provide the names and addresses of all owner/operators to whom you sold any of the APUs listed on attached Exhibits A1 and B1. If you have information indicating that any of these owners/operators sold the vehicle on which the defective APU was installed, please provide the names and addresses of the owners/operators to whom the vehicle was sold. Please provide this information to Idle Free at [warranty@idlefreesystems.com](mailto:warranty@idlefreesystems.com).
- For additional information regarding Series 1000, formally BA-600 (installation instructions, warranty, reimbursement information or standard labor hours), please refer to the dealer portal at [idlefreetechnology.com](http://idlefreetechnology.com). A login is required. Contact Idle Free Customer Service at [warranty@idlefreesystems.com](mailto:warranty@idlefreesystems.com) if you do not have a dealer login.