

Hello technicians,

Many parts of the United States are seeing a great deal of snow this year. With this snow comes many chemicals on our roadways like sodium chloride, magnesium chloride, and calcium chloride. While these chemicals have the benefit of keeping roads clear for safety, they are extremely corrosive to metals and especially exposed electrical connections.



As always, we recommend lifting the hood on all APUs every time a truck is in the shop for



maintenance to inspect harnesses and all connections for corrosion and tightness. When you have the inside of the APU exposed it is highly recommended to wash it with water to eliminate as much of the chemicals as possible. If the truck needs to be washed, so does the APU.

Make sure to use a low-pressure source on the condenser coil so that no fins are bent or damaged. For more information on routine maintenance please visit our customer portal.

For help or questions with any eAPU issues please contact us.

Tech Support Phone: (920) 206-9333

Tech Support email: techsupport@idlefreesystems.com