



Defect A: Frame Rework Decision Tree



Defect B: Mounting Decision Tree



*Please contact IFS Customer Service if the remediation kit does not work with your current application




Figure 1 – Area to review



Figure 2 - Frame gusset in place